

**Morgan  
Electro Ceramics**232 Forbes Road  
Bedford

Ohio 44146-5418

USA

Tel: (440) 232-8600

Fax: (440) 232-8731

[www.morganelectroceramics.com](http://www.morganelectroceramics.com)

March 24, 2000


Ms. Nancy Mugavero  
USEPA Region 5  
77 West Jackson Blvd. AE-17J  
Chicago, IL 60604-3507

RE: Exception Report for NESHAP, Ohio EPA ID L001

Dear Ms. Mugavero:

Morgan Electro Ceramics has submitted the Annual Report for Halogenated Solvent Cleaning Machines for RY 1999 and has shown an exception for Ohio EPA ID L001 for the three-month rolling average from 12/31/99 to 10/01/99. The inherent reason for the exception was due to mechanical problems with the degreaser. As a corrective action, the recirculating pump/motor assembly, high temperature control display, and thermocouples were replaced on 12/7/1999. The emission estimates for both prior three-month rolling averages showed values of 20.23 lbs/month/sq. ft. surface area and 16.4 lbs/month/sq. ft. surface area respectively. If you have any further questions, please contact me at (440) 232-8600.

Sincerely,



William J. Hocevar, P.E.  
Facility Manager

cc: D. Mehls

